




BUILDING SAFETY CERTIFICATE

The building of Woods Park Sainik School Hamirpur at Bani, is inspected along with concerned Junior Engineer. The building has neither been designed nor constructed by this department. No earthquake resistant norms have been adopted for this building. No structure drawing approved by the competent Government Agency have been produced. The structure is a non Engineering structure. Hence the structure safety of this building can not be ensured specially from earthquake point of view. The year of construction of this building is 2010 as intimated by the concerned School owner. This department will not be responsible for any type of loss of life and property etc., if this structure falls under any circumstances. However as per visual appearance, the building seems safe for functioning for the year/academic session 2024-2025 to 2026-2027.

  
Junior Engineer,  
HPPWD Section,  
Barsar-11

  
Assistant Engineer  
H.P.P.W.D. Sub Division  
Barsar

  
Executive Engineer  
Barsar Division  
H.P.P.W.D. Barsar